

Service, solutions and support

Fans and blowers

Weir Minerals Services has high level skills and experience in fan and blower installation, relocation, retrofits, upgrades, overhauls, servicing, fault analysis, alignment and component manufacture for a range of equipment.

Further, with our extensive history in equipment design and manufacture we have the in-house expertise to implement changes to equipment to improve efficiencies and reduce the total cost of ownership.

Capabilities include:

- fan and blower overhauls from total project management, to supervision to responsibility for overhaul with provision of supervisory, trades and assistance labour
- on-site machining for rectification and retrofit works working to close tolerances
- machinery alignment with equipment regularly calibrated in accordance with manufacturers' recommendations, supported by in-house noise and vibration specialists with in-depth experience in analysis, solutions and rectification
- mobile containerised workshops for on-site activities
- re-engineered components can be manufactured within minimum timeframes. Combined with analysis of latest materials technology, the manufacturing of specific components to complete equipment is one of our key strengths

Equipment experience includes:

- Donkin
- Howden
- Hurl
- Robuschi
- Roots



(Top) On-site refurbishment of forced draft (FD) fan.
(Centre) Workshop overhaul of Donkin blower for water treatment plant. (Bottom) On-site overhaul of sewerage treatment aeration blower. (Left) Installation and commissioning of blower.

Meeting the needs of customers worldwide



Field Services	HQ	Somersby	15 Gindurra Road Somersby NSW 2250	Tel: +61 2 4349 2999 Fax: +61 2 4349 2900
Service Centres	NSW	Beresfield	9 Arunga Drive Beresfield NSW 2322	Tel: +61 2 4032 9400 Fax: +61 2 4032 9497
		Wollongong	Lot 2/17 John Cleary Place Coniston NSW 2500	Tel: +61 2 4227 4022 Fax: +61 2 4227 4088
	QLD	Rockhampton	80 McLaughlin Street N Rockhampton QLD 4701	Tel: +61 7 4924 7700 Fax: +61 7 4924 7799
	VIC	Sale	24 Hunt Place Wurruk VIC 3850	Tel: +61 3 5144 5933 Fax: +61 3 5144 1708
	WA	Henderson	20 Stuart Drive Henderson WA 6166	Tel: +61 8 9410 7500 Fax: +61 8 9410 7510
		Kalgoorlie	30 Atbara Street Kalgoorlie WA 6430	Tel: +61 8 9021 1454 Fax: +61 8 9021 1468
Bunbury		1 Shanahan Road Bunbury WA 6230	Tel: +61 8 9726 2301 Fax: +61 8 9726 2303	

Weir Minerals Australia Ltd		Excellent Minerals Solutions
Services Headquarters:		WEIR
15 Gindurra Road	Tel: +61 2 4349 2999	MINERALS
Somersby NSW 2250	Fax: +61 2 4349 2900	
Australia	www.weirminerals.com	