

Worldwide Service Network

Bunbury Service Centre

Weir Minerals Services provides leading edge engineered products and services to diversified industrial markets, supported by a national network of state-of-the-art Service Centres.

The Bunbury Service Centre provides in-house engineering support, maintenance and service - in particular the repair and overhaul of slurry and vertical pumps, valves and hydrocyclones - and field service support.

The Service Centre is located 191 kilometres south of Perth close to the large mining sector of south east Western Australia.

The Bunbury Service Centre is certified to Quality Assurance System ISO 9001:2000 and Environmental Management System ISO 14001:2004 and works to a Lean Manufacturing System



Bunbury Service Centre plant capabilities:

Lifting capacity	1 x 5t cranes 1 x gantry crane electric hoist
Hydraulic press	60t vertical press
Forklift	3.5t gas
Hydrostatic testing	Test plates to 350mm discharge and 6000psi test pump. Slurry valve test bench
Painting capabilities	2.5m open face spray booth
Bearing capabilities	Purpose-built pressurised clean room for building bearing assemblies in clean environment. 56 bearing assemblies as rotatable stock



Bunbury Service Centre contact details:

1 Shanahan Road
Bunbury WA 6230

Tel: +61 8 9726 2301
Fax: +61 8 9726 2303

(Top) Bunbury Service Centre, 119kms south of Perth.
(Centre left) Bearing assembly clean room.
(Centre right) Slurry valve testing.
(Bottom) Pump rebuild in Bunbury Service Centre.

Meeting the needs of customers worldwide



Field Services	HQ	Somersby	15 Gindurra Road Somersby NSW 2250	Tel: +61 2 4349 2999 Fax: +61 2 4349 2900
Service Centres	NSW	Beresfield	9 Arunga Drive Beresfield NSW 2322	Tel: +61 2 4032 9400 Fax: +61 2 4032 9497
		Wollongong	Lot 2/17 John Cleary Place Coniston NSW 2500	Tel: +61 2 4227 4022 Fax: +61 2 4227 4088
	QLD	Rockhampton	80 McLaughlin Street N Rockhampton QLD 4701	Tel: +61 7 4924 7700 Fax: +61 7 4924 7799
	VIC	Sale	24 Hunt Place Wurruk VIC 3850	Tel: +61 3 5144 5933 Fax: +61 3 5144 1708
	WA	Henderson	20 Stuart Drive Henderson WA 6166	Tel: +61 8 9410 7500 Fax: +61 8 9410 7510
		Kalgoorlie	30 Atbara Street Kalgoorlie WA 6430	Tel: +61 8 9021 1454 Fax: +61 8 9021 1468
		Bunbury	1 Shanahan Road Bunbury WA 6230	Tel: +61 8 9726 2301 Fax: +61 8 9726 2303

Weir Minerals Australia Ltd

Services Headquarters:

15 Gindurra Road
Somersby NSW 2250
Australia

Tel: +61 2 4349 2999
Fax: +61 2 4349 2900

www.weirminerals.com

Excellent
Minerals
Solutions

